



- 1. Low Pressure setting spindle
- 2. Differential setting spindle
- 3. Low Pressure Main arm
- 4. Low Pressure Main spring
- 5. Differential spring
- 6. Low Pressure Bellows
- 7. High Pressure setting spindle
- 8. High Pressure Main arm
- 9. High Pressure Main spring
- 10. High Pressure Bellows
- 11. Contact system
- 12. Terminal
- 13. Ground terminal
- 14. Cable entry
- 15. Brass nuts

Design		No.	2022/4/2
		DATE	

PRESSURE CONTROL DRAWING	

060-124566R		1:1	
	2		

РИДАН